

Draft Inducer Cross Reference Guide

for WATER HEATERS and FURNACES



FASCO

The replacement motor and
blower specialist.

Distributed by

MARS[®]

www.mar-sm-a.com



WATER HEATER DRAFT INDUCER



OEM/COMPETITOR PART #	OEM MODEL #	REPLACEMENT PART #
AO Smith Replacement Water Heater Draft Inducers		
7021-10770	183505-000	W2 NEW
7021-10910	183381-000	W4 NEW
Bradford White Replacement Water Heater Draft Inducers		
7021-9764	239-4061 4-00C	W6 NEW
7021-10712	239-42133-00B	W5 NEW
FASCO Replacement Water Heater Draft Inducers		
7021-10060		W1 NEW
GSW Replacement Water Heater Draft Inducers		
7021-8347	63217	W7 NEW
7021-9756	63172	W8 NEW
State Ind. Replacement Water Heater Draft Inducers		
7021-10548	0012400500	W9 NEW
7021-11086	0012400540	W10 NEW



www.marsm-a.com

FURNANCE DRAFT INDUCER

OEM/COMPETITOR PART #	OEM MODEL #	REPLACEMENT PART #
Air Plus/ Scherba Ind Replacement Draft Inducers		
7062-3496		A087
7062-4687	PA146	A087
Aladdin Steel Ind Replacement Draft Inducers		
7002-2983	230-1460	A120 NEW
Amana Ind Replacement Draft Inducers		
7021-7794	D986868	A280 NEW
7021-8730	D9868617	A283 NEW
7021-9316	105854-04	A185 NEW
7021-9398	11096904	A286 NEW
7021-9625	20190601	A180 NEW
7021-9655	10585405	A287 NEW
Consolidated Ind. Replacement Draft Inducers		
7021-6376	TF302065	A128
7021-9404		A128
7021-10271	4MH24	A128
Excel Replacement Draft Inducers		
7058-0280	20093603	A100
Fedders Replacement Draft Inducers		
	11-7096	A159
	AK4K84BX	A159
7073-0565	4MH48	A159
	8353920103	A161
Franklin Replacement Draft Inducers		
	80270	B23617
	80270	B23618
7021-10288	4MH41	B23617
7021-10289	4MH42	B23618



www.marsm-a.com

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Goodman Replacement Draft Inducers		
7002-2307	B1859005	A157
7002-2407	20044401	A160
7002-2771	4MH09	A157
7002-3036	B4059000	A182
7002-3219	R7-RFB185	A157
7021-6804	B1859000	A079
7021-7302	D9868620	A189
7021-7794	D986868	A280
7021-8252	D6996405	A281
7021-8448	B18590505	A282
7021-8656	B295900	A162
7021-8730	D9868617	A283
7021-9064	11009001	A129
7021-9087	B2833001	A140
7021-9227	D9886202	A284
7021-9236	B2833002	A285
7021-9259	11009002	A129
7021-9316	10585404	A185
7021-9398	11096904	A286
7021-9565	B2833001S	A140
7021-9574	11009003	A129
7021-9625	201-90601	A180
7021-9655	10585405	A287
7021-9727	11177202	A288
7021-9915	FB-RFB140	A140
7021-9924	R7-RFB129	A129
7021-10006	20028901	A187
7021-10262	4MH15	A079
7021-10272	4MH25	A129
7021-10279	4MH32	A140
7021-10958	B4833000	A188
7058-0081	20351402	A289
7058-0136	200-44403	A181
7058-0229	B4059001	A184
7062-3151	D98686-7	A158
7062-4774	D9868614	A158
7062-5015	20245903	A290



OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Heil Quaker Replacement Draft Inducers		
7021-5043	610672	A064
7021-7102	5C085	A064
ICP Replacement Draft Inducers		
7002-1891	1708-600P	A175
7002-2633	1010975	A172
7002-2792	1010975P	A172
7002-2946	1011899	A176
7021-7617	HQ1054268FA	A148
7021-7700	1708-607	A134
7021-8693	1006168P	A179
7021-8735	1708-607P	A134
7021-8736	1708-607P	A134
7021-8741	1094073	A141
7021-8742	1094073P	A141
7021-8918	1010312	A170
7021-9188	1010239	A174
7021-9237	1054268P	A148
7021-9277	1010238	A302
7021-9335	1010324	A134
7021-9362	1010526	A170
7021-9477	1010238P	A134
7021-9498	1010239P	A301
7021-9499	1010324P	A302
7021-9594	1010928	A170
7021-9700	1011022	A304
7021-9701	1011021	A304
7021-9914	RFB-141	A141
7021-9918	R7-RFB134	A134
7021-9935	1011095	A170
7021-9936	1011097	A170
7021-10048	1110008	A169
7021-10275	4MH28	A134
7021-10280	4MH33	A141



OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

ICP Replacement Draft Inducers (con't)			
7021-10284	4MH37	A148	
7021-10287	4MH40	A151	
7021-10299	1011409	A170	
7021-10363	1011632	A177	
7021-10580	1085571P	A169	
7021-10702	1164280	A170	
7021-10928	1013188	A178	
7062-3793	1008695	A145	
7062-3794	1008416P	A307	NEW
7062-3891	1008695P	A145	
7062-4061	1009924	A145	
7062-4201	1010491	A171	
7062-4274	1010527P	A171	
7062-4532	1097245	A306	
7062-4549	1011096	A171	
7062-4578	1011350	A173	
7062-4703	4MH47	A145	
7062-4705	1011410	A171	
7062-4783	1011412	A171	
7062-4832	R7-RFB350	A173	
7062-5165	1149097	A307	NEW
	HQ1050144	A151	

Johnson Furnace Replacement Draft Inducers			
AO Smith	464	A085	

Lennox Replacement Draft Inducers			
7002-2975	313L5501	A200	
7021-8372	T6-2118	A205	
7021-8473	65204100/20J8901	A206	
7021-8657	20J8101	A138	
7021-8812	33J4101	A135	
7021-8819	33J4101P	A135	
7021-8825	20J8101P	A138	

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Lennox Replacement Draft Inducers (con't)			
7021-8959	60J4201	A218	NEW
7021-8983	20J8901	A206	
7021-9001	T6-2118P	A205	
7021-9242	10K5101	A164	
7021-9262	88J3901	A219	NEW
7021-9311	10K5301	A164	
7021-9450	67K0401	A163	
7021-9455	27K5201	A164	
7021-9466	27K6101/65256500	A320	NEW
7021-9593	43K4101/88K8401	A164	
7021-9640	10K5301P	A164	
7021-9657	27K5201P	A164	
7021-9884	24L0101	A322	NEW
7021-9917	R7-RFB135	A135	
7021-10046	40425-003	A155	
7021-10055	41144-001/H	A201	
7021-10108	43K4101P	A164	
7021-10276	4MH29	A135	
7021-10277	4MH30	A138	
7021-10302	FB-RFB547	A163	
7021-10325	40425-002	A155	
7021-10376	18L0401	A213	NEW
7021-10602	45037-001	A202	
7021-10721	67K0401P	A163	
7021-10743	41144-001S	A201	
7021-10841	49L5301	A203	
7021-10915	60L1401	A216	NEW
7021-11042	R7-RFB43	A164	
7021-11062	R7-RFB425	A155	
7021-11063	18M6701	A210	
7021-11106	45037-1P	A202	
7021-11174	46087-001	A202	
7021-11231	25M5501	A217	NEW
7021-11406	83L4101	A204	
7021-11634	81M1601	A211	
7058-0217	60M7901	A207	
7058-0322	60M8101	A208	

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Lennox Replacement Draft Inducers (con't)			
7062-1794	23G8101/ ARMSTG43797-001	A323	
7062-1909	28G6601	A324	NEW
7062-2845	98G8701	A325	NEW
7062-4819	19L1501	A329	NEW
7062-5441	38M5001	A209	
7062-5546	69M3301	A330	NEW
7062-5554	69M3201	A331	NEW

Magic Chef Replacement Draft Inducers			
7021-10264	4MH17	A081	
	35035B001	A081	
	322P859,DE3L038	A081	
	HWC Series:		
	48HWC24A,		
	48HWC181,		
	35HWC181, 60HW,		
	60HWC24A,		
	60HWC181, 48HW,		
	60HWC30A,		
	66HWC18A,		
	36HWC241, 66HW,		
	60HWC241,		
	66HWC181,		
	66HWC241,		
	60HWC301,		
	48HWC241,		
	66HWC301,		
	48HWC18A,		
	60HWC18A,		
	36HWC18A,		
	66HWC24A, 36HW,		
	36HWC24A	A081	

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Nordyne Replacement Draft Inducers			
7002-3158	6219500	A126	
7021-7975	6212850	A132	
7021-9132	6212850	A131	
7021-10159	6217000	A131	
7021-10273	4MH26	A131	
7021-10274	4MH27	A132	
7021-10381	6217930	A121	
7021-10493	R7-RFB903	A132	
7021-11227	6219490	A122	
7021-11385	622064	A123	
7021-11379	6219290	A124	
7062-4159	6216130	A130	
7062-4538	FB-RFB130	A130	
7062-4698	4MH43	A130	

Rheem Replacement Draft Inducers			
7021-5239	74-70-21496-01-06	A090	
7021-5615	74-70-21496-03-01	A079	
7021-5990	70-21876-01	A086	
7021-6967	70-42241-01	A244	
7021-7104	5C088	A086	
7021-7105	5C087	A086	
7021-7150	70-22436-01	A242	
7021-7490	70-42278-02	A245	
7021-7577	AP10983-4	A139	
7021-7790	70-22436-02	A243	
7021-8183	70-21496-83	A240	
7021-9567	70-23641-81	A241	
7021-9969	R7-RFB139	A139	
7021-10262	4MH15	A079	
7021-10266	4MH19	A086	
7021-10268	4MH21	A090	
7021-10278	4MH31	A139	
7062-1881	70-22165-81	A142	

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Rheem Replacement Draft Inducers (con't)		
7062-2615	5C089	A142
7062-2615	5C089	A142
7062-3861	70-24033-01-13	A136
7062-3925S	70-24206-01	A246
7062-4534	FB-RFB142	A142
7062-4537	RF-RFB136	A136
7062-4699	4MH44	A136
7062-4702	4MH46	A142
7062-4841	28686	A136
7062-5177	70-24033-01	A136
7062-5272	70-24206-02	A246
7062-5519S	70-100612-01	A247

Skymark Replacement Draft Inducers		
7021-9136	MTR-136PK	A251

Skymark Replacement Draft Inducers		
7021-10260	4MH13	A073
	8251560133	A073
	629932	A073
	8351520243	A073

Trane Replacement Draft Inducers		
7000-5806	D341114G01	A190
7000-5833	C341445P01	A190
7000-5838	X38040336020	A190
7002-2530	D341095P02	A278
7002-2531	D341095P04	A279
7002-2532	D341095P01	A360
7002-2558	D330787P01	A361
7002-3273	D341663P05	A362
7002-3443	D342078P01	A264
7002-3444	D342078P02	A265
7002-3445	D342078P04	A266

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Trane Replacement Draft Inducers (con't)			
7002-3446	D342078P05	A267	
7002-3447	D342078P06	A268	
7021-6681	X38050005007	A075	
7021-6682	X38040252017	A069	
7021-6683	X38040251017	A191	
7021-7833	C661452P01	A150	
7021-7986	21D340096P04	A146	
7021-8013	210340125	A143	
7021-8051	21D340096P02	A367	
7021-8428	210330673	A143	
7021-8569	X38040253057	A192	
7021-8591	X38040050010	A193	
7021-8924	X38040305017	A143	
7021-8925	X38040276047	A146	
7021-8928	X38080029010	A150	
7021-9011	D330757P01	A276	
7021-9055	D330809P01	A143	
7021-9010	D330757P02	A196	
7021-9065	X38040313027	A196	
7021-9396	C665662P01	A373	
7021-9511	D330900P01	A194	
7021-9561	X38020420017	A194	
7021-9913	R7-RFB143	A143	
7021-10259	4MH12	A069	
7021-10261	4MH14	A075	
7021-10281	4MH34	A143	
7021-10283	4MH36	A146	
7021-10286	4MH39	A150	
7021-11054	X38040363010	A269	
7021-11306	D330757P03	A195	
7021-11543	D342094P03	A195	
7021-11543S	X38040313070	A195	
7021-11544	D342094P02	A196	
7021-11544S	X38040313060	A196	

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

Trane Replacement Draft Inducers (con't)		
7058-0259	D342077P01	A198
7058-0260	D342077P02	A199
7058-0261	D342077P03	A260
7058-0262	D342077P04	A261
7058-0263	D342077P05	A262
7058-0264	D342077P06	A263
7062-3616	21D340365P03	A130
7062-3782	D340623P01	A368
7062-3915	C663946P01	A369
7062-3918	C664099P01	A370
7062-3956	D330757P035	A130
7062-3969	38040308	A271
7062-3971	38040309	A272
7062-3972	38040310	A273
7062-3973	38040311	A274
7062-4004	X38040313037	A130
7062-4538	FB-RFB130	A130
7062-4698	4MH43	A130
7062-5033	X38040369010	A270
7092-0238	D342097P01	A197
7092-0238S	X38010571010	A197
Williamson Replacement Draft Inducers		
7021-5510	25-568	A080
7021-6999	100,000 BTU	A118
7021-10263	4MH16	A080
7021-10269	4MH22	A118
York Replacement Draft Inducers		
7002-2941	024-31957-000	A228
7002-3285	024-31957-000	A228
7021-1373	026-20224-700	A083
7021-4314	026-22239-700	A063
7021-5478	2940-391	A088

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

York Replacement Draft Inducers (con't)		
7021-5838	026-27510-700	A220
7021-6691	026-30614-C000	A221
7021-6770	026-29599-700	A144
7021-7217	02-30887-000	A220
7021-7481	026-32067-000	A222
7021-8317	026-32067-700	A222
7021-8318	026-30614-700	A221
7021-8629	2940-391P	A088
7021-8935	2702-321	A156
7021-9054	02-30887-700	A220
7021-9428	024-27519-000	A154
7021-9656	026-33999-001	A223
7021-9908	R7-RFB391	A088
7021-9912	RFB-144	A144
7021-10096	026-33999-001	A223
7021-10213	17452	A231
7021-10257	4MH10	A063
7021-10265	4MH18	A083
7021-10267	4MH20	A088
7021-10282	4MH35	A144
7021-10300	024-27519-000	A154
7021-10675	024-27653-000	A231
7021-10882	2702-321P	A156
7021-11577	17503	A225
7021-11577S	024-34558-000	A225
7058-0266	17500	A226
7058-0266S	024-34490-000	A226
7058-0267	024-32052-000	A229
7058-0267S	024-32085-000	A229
7062-2442	024-25007-000	A137
7062-2442	024-25007-000	A147
7062-3342	024-25007-700	A137
7062-3342	024-25007-700	A147
7062-3484	024-25057-000	A137

OEM/COMPETITOR PART # OEM MODEL # REPLACEMENT PART #

York Replacement Draft Inducers (con't)		
7062-3958	024-25960-000	A165
7062-4236		A137
7062-4417		A147
7062-4536	RFB-137	A137
7062-4536	RFB-137	A147
7062-4701	4MH45	A137
7062-4701	4MH45	A147
7062-4708	024-27641-000	A227
7062-4708S	024-27641-000	A227
7062-4743	024-27654-000	A224
7062-5019	20000101	A168
7062-5048	024-27654-000	A224
7062-5094	024-31953-000	A230
7062-5094S	024-31953-000	A230
7062-5155	102529	A234
7062-5267	026-39532-000	A234

Locate the OEM part or model number on the draft inducer you need to replace and use this simple guide to find the FASCO direct replacement. Every effort has been made to insure the accuracy of this reference guide. Design changes may result in different operating characteristics or dimensional changes from one manufacturer to another. Therefore, FASCO cannot accept responsibility for the ultimate selection. Always compare draft inducers for interchangeability prior to installing or recommending their use.

GUIDE TO OEM BRAND NAMES

OEM	OEM BRANDS	OLD OEM NAMES	SERV. BRAND
Carrier	Carrier, Bryant Day & Night, Heil, Tempstar, Comfortmaker, Arcoaire, Kenmore	Payne Whirlpool	RCD Fast Parts
Goodman	Janitrol, Amana		
Trane	Trane, American Standard	General Electric	Service First
Lennox	Lennox, Armstrong, Air-Ease, Excel, Advanced Dist. Prods, Heatcraft, Bohn	Magic Chef, Ducane	
Rheem	Rheem, Ruud, Weather King		ProStock, Pro-Tech
York	York, Luxaire, Fraser-Johnston, Evcon, Coleman	Henry Moncreif, Borg-Warner	Source1
Nordyne	Intertherm, Miller, Frigidaire, Tappan, Philco, Gibson, Maytag, Kelvinator, Westinghouse, Grandaire	Lear-Siegler	
Burnham	Thermo Pride, Burnham		
ECR	Olsen, Duo-Matic, Olsen, Utica, Dunkirk		

ABOUT DRAFT INDUCED BLOWERS

Many of the new energy-efficient gas furnaces use induced draft blowers to control flue gas. All induced draft blowers incorporate some type of signaling device to alert the furnace that the induced draft blower is operating. Some use a sail switch in the exhaust air stream. Others utilize a centrifugal switch or electronic sensor built into the motor, and some use a static pressure tap in the blower housing. All blowers are intended to provide air flow prior to ignition.

In today's furnace market, draft inducers are becoming a common replacement part. Since these furnaces are being designed with specific induced draft blowers, it is very important that replacements are installed using exact replacements. It is important that the replacements match the original blower for safety reasons.

These blowers play an important part in controlling the availability of gas to the burners. Most blowers will employ either a centrifugal switch, electronic sensor, or a vacuum tap to generate a signal to the gas valve that the induced draft blower is operating. This feature is necessary to prevent the gas valve from being turned on prematurely or in the event the blower does not operate properly.

These blowers control the removal of the burnt by-products. Therefore, only replacement blowers made for specific furnaces or water heaters should be used for these replacements. The following example describes why.

The blower is designed to produce a certain amount of air-flow measured in CFM (cubic feet per minute). The airflow in some furnaces is needed to create a specific amount of vacuum at the vacuum tap mentioned above. If the replacement blower is not the exact one needed but "looks close," it may produce a lesser vacuum at the vacuum tap. This may not allow the furnace to operate since the furnace will not think the induced draft blower is operating.



Toll Free (800) 445-4155

Fax (631) 348-7160

website: www.marsm-a.com